

Appendix C: Site Photographs



Appendix C: Site Photographs



Photo 1: External fencing. Photo 2: Newly completed access road. Photo 3: Parking area and internal fence. Photo 4: Northern portion of the erf



Appendix C: Site Photographs



Photo 5 & 6: Completed access road over tidal channel. Photo 7: Culvert with access control, shows height of water moving through at high tide. Photo 8: Exposed mudflats of the tidal channel showing improved water quality and habitat.



Appendix C: Site Photographs



Photo 9: Exposed mudflats of tidal channel at low tide. Photo 10: Thicket on the northern portion of the erf. Photo 11: South view of the southern portion of the erf with old dam in foreground. Photo 12: Northern portion of the erf

