



Photos 1: View from north to south of the extent of the facility showing all the accommodation units, store and laundry.



Photos 2: View from west to east of the three sea facing units.





Photos 3 – 4: View of the gardened area between the beach front units and the inland units. Note the exotic tree species in Photo 4. Photo 5 shows the servitude road along the eastern boundary. Photo 6 shows the indigenous vegetation in front of the sea facing units.







Photo 7: View of the existing raised stairway from the beach to the front sea facing units. This access provides beach access for the entire resort.



Photo 8 - 10: Views of the area between the accommodation units showing the paths, raised garden beds, fences, buildings and braai areas.





PHOTO KEY DIAGRAM





Photos 1,2,3 (left-to-right): Read Road Access, Existing Admin/ Reception/ North-facing view from beach.



Photo 4: South-facing view from Read Road.



Photo 5: South-facing showing Read Road (right) and internal gravel access road just beyond pillar/ timber fence in foreground of image.



Photo 6: Typical view of existing cottages set within indigenous trees.



Photos 7,8,9 (left-to-right): Simple outbuilding/laundry with covered area along western property boundary/ South-facing view through tree canopy.



Photo 10: North-facing view from directly behind three units fronting directly onto the coastline.

3



Photo 11: South-facing view of three units overlooking the beach.



Photos 12,13,14: Three units and timber decking leading onto the beach.



Photo 15: North-facing contextual view of the property from beach.

Arch Rock

Source: Perception Planning

Ref: BIT634