

## Appendix D: Site Photographs





## Appendix D: Site Photographs



Photo 1 – dam view from the N9. Photo 2 shows clearance activities in 2019. Photos 3 & 4 view the dam from the eastern side.





## Appendix D: Site Photographs



View from the western side of the wall of the dam. (Photos 5, 6 & 7). Note bluegum infestation upstream. Photo 8 shows the current spillway.





## Appendix D: Site Photographs



View of the dam wall (Photo 9 & 10).  
Photo 10 shows the area downstream of the wall in 202, with the comparison for 2019 during the clearing operations. Note the regrowth in the riparian area.

